

Automotive Industry

## TOP FAULT COMPLAINT

Vehicle Type : Passenger Car

QM Department

F-QM-161-274

**COMPLAINT NO. :** FC - QM No. 4362

**Complaint Area :** Q-Gate Paintshop

- + Model : **GLC300 4 MATIC AMG** BodyNo : **6132724** Prod No : Paint Color : **149**
- + Check Date : **15-Jan-19** Time : **6:50 PM** Detected by : **Q-Gate Paintshop Inspector -- Minh**
- + Agreed Fault classification for complaint : **Prio 2** Fault Location : **N080426-2** Fault Code: **K7D**
- + Informed to Process Owner : **CS1 - Paintshop AM** \_ **Mr. Toan** Shift : **Shift 2**
- + **Problem / Fault Description :**  
**Open sealer at rear door RH**



+ **Root Cause :**

### FAULT ESCALATION IMPEM

No.	Body No. / Prod No.	Inspection Date	Result	
			OK	NOK

### DYNAMIC CHECK (5 VEHICLES BACKWARD)

1				
2				
3				
4				
5				

### DYNAMIC CHECK (5 VEHICLES FORWARD)

1				
2				
3				
4				
5				

<b>8D Report issued :</b>	<b>Inspector :</b>	<b>Supervisor :</b>
---------------------------	--------------------	---------------------